Media Interface Plus - Functions Overview

Class	Model	MY	iPod / iPhone Audio[1]	iPod / iPhone Video[2]	Bluetooth Audio Streaming[3]	Pandora Internet Radio[4]	Charging mobile device[5]	Phonebook Download[6]	Email / Text Message Reading & Reply[8]
C-Class	W204	MY10	◇	Θ	◇	◇	◇	◇[7]	◇
C-Class	W204	MY11	◇	Θ	◇	◇	◇	◇[7]	◇
E-Class	A/C207	MY10	○	Θ	○	○	○	○	○
E-Class	W/S211	MY09	○	○	○	○	○	○	○
E-Class	W/S212	MY10	○	Θ	○	○	○	○	○
S-Class	V221	MY10	□	Θ	Θ	□	□	□	□
S-Class	V221	MY11	□	Θ	Θ	□	□	□	□
S-Class	V221	MY12	□	Θ	Θ	□	□	□	□
CL-Class	C216	MY10	□	Θ	Θ	□	□	□	□
CL-Class	C216	MY11	□	Θ	Θ	□	□	□	□
CL-Class	C216	MY12	□	Θ	Θ	□	□	□	□
CLS-Class	C219	MY09	◇	◇	◇	◇	◇	◇	◇
CLS-Class	C219	MY10	Δ	Δ	Δ	Δ	Δ	Δ	Δ
CLS-Class	C219	MY11	Δ	Δ	Δ	Δ	Δ	Δ	Δ
GLK-Class	X204	MY10	◇	Θ	◇	◇	◇	◇[7]	◇
GLK-Class	X204	MY11	◇	Θ	◇	◇	◇	◇[7]	◇
GLK-Class	X204	MY12	◇	Θ	◇	◇	◇	◇[7]	◇
M-Class	W164	MY09	○	○	○	○	○	○	○
M-Class	W164	MY10	○	○	○	○	○	○	○
M-Class	W164	MY11	○	○	○	○	○	○	○
R-Class	V251	MY09	○	○	○	○	○	○	○
R-Class	V251	MY10	○	○	○	○	○	○	○
R-Class	V251	MY11	○	○	○	○	○	○	○
R-Class	V251	MY12	○	○	○	○	○	○	○
GL-Class	X164	MY09	○	○	○	○	○	○	○
GL-Class	X164	MY10	○	○	○	○	○	○	○
GL-Class	X164	MY11	○	○	○	○	○	○	○
GL-Class	X164	MY12	○	○	○	○	○	○	○
G-Class	W463	MY09	□	□	□	□	□	□	□
G-Class	W463	MY10	□	□	□	□	□	□	□
G-Class	W463	MY11	□	□	□	□	□	□	□
G-Class	W463	MY12	□	□	□	□	□	□	□
SLK-Class	R171	MY09	Δ	Δ	Δ	Δ	Δ	Δ	Δ
SLK-Class	R171	MY10	Δ	Δ	Δ	Δ	Δ	Δ	Δ
SLK-Class	R171	MY11	Δ	Δ	Δ	Δ	Δ	Δ	Δ
SL-Class	R230	MY09	□	□	□	□	□	□	□
SL-Class	R230	MY10	□	□	□	□	□	□	□
SL-Class	R230	MY11	□	□	□	□	□	□	□
SL-Class	R230	MY12	□	□	□	□	□	□	□
SLS-Class	C197	MY11	□	Θ	□	□	□	□[7]	□
SLS-Class	C197	MY11	□	Θ	□	□	□	□[7]	□

Θ Feature not applicable on these models.
1 Audio support through a connected iPod / iPhone

2 If factory Rear-Seat Entertainment System present iPod / iPhone video content can be displayed in the rear of the vehicle. To eliminate driver distraction, video will not play in the COMAND screen while driving.
3 Requires Bluetooth capable phone and pairing with the MIP. Only phones that support multiple Bluetooth profiles (iPhone & BlackBerry) are able to stream audio content and allow for Hands-Free Calling at the same time. Please check with your mobile device's owners manual if such functionality is supported. Not recommended for iPhone as it can be connected to cable and charged.
4 Full integration of Pandora Internet Radio only possible with a connected iPod / iPhone. Controls enabled through the MIP menu within in the COMAND system, steering wheel buttons, COMAND control buttons, and central controller. For other phones please refer to Bluetooth Audio Streaming for the Pandora application. Controls of Pandora only on mobile device.
5 Charging via connected iPhone. For all other phones MIP offers charging that requires additional USB cable that can be provided by your mobile device carrier.
6 In order to download the address book, the mobile device has to be paired via Bluetooth protocol with the MIP and the MIP has to be paired with COMAND.
7 Phonebook download will result in multiple entries after initial download. Replacing or deleting existing entries not possible unless Radio is reset to factory settings.
8 Please note that currently only selected BlackBerry mobile phones support this functionality. The mobile device needs to have OS6 running. Please contact your wireless carrier to ensure your device is capable.

Δ **All vehicles with P01**
□ **All vehicles**
◇ **All vehicles with Multimedia Package**
○ **All vehicles with P01 or P02 package**